



Rid That Canopy Of That Ugly Seam

I was looking over the F-15 tonight and noticed a seam running down the middle of the canopy...



So here is how I fixed it....

First here are the tools I used, #11 x-acto knife, tri-grit sanding stick and future floor polish (now pledge floor wax)




First I started by scraping down the seam with the #11 blade edge. You can tell which side is higher by the straight line that appears (look at the bottom edge of the canopy in the picture below)



Once you finish this step it will look like this...



I then sand it down with the rough grit on the tri grit sanding stick and it looks like this when done...



Next I use the middle grit to start the buffing out of the scratches...



then I use the buffing side of the sanding stick to get to this stage...



When all that is done to my satisfaction I coat it in future...



and unless you know exactly where to look the seam is gone...